

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2018

Submitted Date:

09/13/2018

Document Number:

689301909**FIELD INSPECTION FORM**Loc ID 335370 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	<a href="#">all Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274756	WELL	PR	04/11/2005	GW	045-13388	COX 33-1 (B33NE)	PR
274757	WELL	PR	04/15/2005	GW	045-13387	COX 33-3A (B33NE)	PR

**General Comment:**

[Follow up inspection Doc#689301681 . Required Corrective Action items noted in previous inspections have been satisfied.](#)

[Equipment inventory has not changed on location.](#)

[Battery containment appears to have been sprayed with micro blaze treatment.](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Heated Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 274756 Type: WELL API Number: 045-13388 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 274757 Type: WELL API Number: 045-13387 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Compaction				
Seeding						
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301910	Inspection photo 689301910	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578600">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578600</a>