

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401643248
Date Received:
05/17/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		SanJuanCOGCC@bp.com Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602570
Inspection Date: 03/21/2018 FIR Submit Date: 04/03/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326344

Location Name: WEBB-REEDER GAS UNIT B- N34N9W Number: 11SENW County: LA PLATA
Qtrqr: SENW Sec: 11 Twp: 34N Range: 9W Meridian: N
Latitude: 37.224548 Longitude: -107.825572

FACILITY - API Number: 05-067- -00 Facility ID: 216268

Facility Name: WEBB-REEDER B Number: 1
Qtrqr: SENW Sec: 11 Twp: 34N Range: 9W Meridian: N
Latitude: 37.224548 Longitude: -107.825572

CORRECTIVE ACTIONS:

1 ☒ CA# 115505

Corrective Action: Maintain stormwater controls and apply further stabilization measures in areas of active erosion (specifically in the eastern project area). Date: 05/04/2018

Response: CA COMPLETED Date of Completion: 05/01/2018

Operator Comment: Storm water BMP's previously installed were repaired on 5/1/18. Additional BMP installed to control erosion rilling that had started. Other work completed during storm water repairs as noted in attached document. See attached document for all work completed with photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Storm water BMP's previously installed were repaired on 5/1/18. Additional BMP installed to control erosion rilling that had started. Other work completed during storm water repairs as noted in attached document. See attached document for all work completed with photos.
Additioinal work performed, but not noted on inspection consisted of clean up of operator and landowner debris found on location, clean up of stained soils around the well head and repair/replacement of well sign. Please see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/17/2018 7:19:38 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401643248	FIR RESOLUTION SUBMITTED
401643263	CA and other work completion photos

Total Attach: 2 Files