

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2018

Submitted Date:

09/07/2018

Document Number:

689801626**FIELD INSPECTION FORM**Loc ID 424294 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10339Name of Operator: GULFPORT ENERGY CORPORATIONAddress: 14313 N. MAY AVENUE - SUITE 100City: OKLAHOMA CITY State: OK Zip: 73134**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Seal, Jeff		jseaj@gulfportenergy.com	EHS Director; All Inspections
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424295	WELL	PR	03/02/2012	OW	081-07666	ELLGEN 11-10-1	PR

**General Comment:**

Routine FIU inspection in response to fire on 9/6/2018.

9/12/2018 Revision: This inspection is being amended to clarify that COGCC did not intend to resolve the alleged violations noted herein without the imposition of a penalty, pursuant to Rule 522.c. Instead, COGCC will be following up on this inspection and determining how best to resolve the alleged violations after COGCC's investigation has concluded.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-216-9119 is cell number for pumper. Emergency number listed on location signs no longer is manned 24/7. Stickers with this new number have been ordered and will be placed on location upon receipt.

9/12/2018 Revision: This inspection is being amended to clarify that COGCC did not intend to resolve the alleged violations noted herein without the imposition of a penalty, pursuant to Rule 522.c.

Corrective Action: Immediately install sign to comply with Rule 210.

Date: 09/07/2018

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	
Condensate	Treater	<= 1 bbl	
Comment:	<p>Stained gravel around base of combustor. Operator plans to remove and properly dispose of all stained gravel and soil.</p> <p>9/12/2018 Revision: This inspection is being amended to clarify that COGCC did not intend to resolve the alleged violations noted herein without the imposition of a penalty, pursuant to Rule 522.c.</p>		
Corrective Action:	Immediately control and contain spills/releases and clean up per Rule 906.a. Immediately contact COGCC EPS staff.		Date: 09/07/2018

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		

Comment:		
Corrective Action:		Date:
Type	PUMP JACK	
Comment:		
Corrective Action:		Date:

<b>Equipment:</b>		corrective date
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	#	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	<p>Fire was caused when back pressure control valve for the heater treater, which was located on the line to the combustor, failed, allowing condensate to be blown towards ignitor.</p> <p>Operator intends to remove valve from proximity to combustor and use methanol for control instead.</p>	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		40.497340,-107.598010
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 424295	Type: WELL	API Number: 081-07666	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Pumping.			
Corrective Action:				Date:

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
		Ditches	Pass			
		Gravel	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Inspector on location in response to phone call received at 7:30 AM 9/7/2018 to notify COGCC of fire caused by equipment failure, resulting in 6.1 acre burn of vegetation on private land immediately adjacent to the location. The fire was caused when back pressure control valve for the heater treater, which was located on the line to the combustor, failed, allowing condensate to be blown towards ignitor. Dried vegetation on location perimeter caught on fire and was extinguished by local fire department.	waldrone	09/07/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401757104	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573339">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573339</a>
689801627	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573337">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573337</a>