

Inspection Photos

Operator: Hilcorp Energy

API: 05-067-08485

Date: 9/10/2018



Photo 1. View of stormwater diversion with outlet on the well pad. It appears cobble was placed in the channel. Cobble is already inundated with sediment. Evidence of recent sediment deposition and stormwater flows observed on the well pad. Corrective action not addressed.



Photo 2. View of sediment deposition and evidence of recent stormwater flows on the well pad, downstream of Photo 1.



Photo 3. View of sediment deposition within the southwestern project area, downstream from photos 1 and 2. Sediment appears to be impeding desirable vegetation. Wire documented in earlier inspection is not addressed.



Photo 4. View of Canada thistles (*Cirsium arvense*) within the eastern project area.



Photo 5. View of musk thistles (*Carduus nutans*) and Canada thistles within the northwestern portion of the project area.