

# Inspection Photos

Operator: Logos Operating

API: 05-067-06443

Date: 9/10/2018



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern project area. Cobble sediment trap is recently installed and appears to be functioning, but is full of sediment and needs maintenance. Revegetation of northern berms and cleaning sediment from diversion will help control erosion.**



**Photo 3. View of cobble run-down in the northeastern project area in good condition.**



**Photo 4. View of cobble run-down in the southern project area in good working condition.**