

Inspection Photo
Clough RWF 512-11
API # 045-12668
Inspection # 689301925



Location Photo #1



Location Photo #2

Inspection Photo
Clough RWF 512-11
API # 045-12668
Inspection # 689301925



Location Photo #3



Location Photo #4, unmarked flowline riser



**Inspection Photo
Clough RWF 512-11
API # 045-12668
Inspection # 689301925**



Location Photo #5, uncontrolled weeds on berm



Location Photo #6, uncontrolled weeds on berm.



Inspection Photo
Clough RWF 512-11
API # 045-12668
Inspection # 689301925



Location Photo #7, uncontrolled weeds on berm.



Location Photo #8, fugitive dust on access road .

**Inspection Photo
Clough RWF 512-11
API # 045-12668
Inspection # 689301925**



Location Photo #9, fugitive dust on access road .



Location Photo #10, fugitive dust on access road .

Inspection Photo
Clough RWF 512-11
API # 045-12668
Inspection # 689301925



Location Photo #11, fugitive dust on access road .



Location Photo #12, fugitive dust on access road .