

Inspection Photos

Operator: BP Production

API: 05-067-08833

Date: 9/13/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is comprised of grasses and shrubs such as smooth brome (*Bromus inermis*), intermediate wheatgrass (*Thinopyron intermedium*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of culvert outlet in the southern project area near the well pad entrance. Erosion controls appear to be functioning.



Photo 4. View of erosional tunneling in the eastern project area that needs repair.



Photo 5. View of sediment deposition from erosion on the northwestern portion of the well pad cut-slope. Sediment controls are needed here.