

Inspection Photos

Operator: BP Production

API: 05-067-09562

Date: 9/13/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is comprised of grasses such as smooth brome (*Bromus inermis*) and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 4. View of the northern project area from the northwestern corner facing eastward.



Photo 5. View of erosional channel approximately 2 feet wide and deep in the northwestern corner of the project area.



Photo 6. View of area along the access, near the well pad entrance, where stormwater flows converge and form an erosional channel that carries sediment down stream toward the well pad.



Photo 7. View of trash in the northern portion of the interim reclamation area.