

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2018

Submitted Date:

09/18/2018

Document Number:

689301931

FIELD INSPECTION FORM

Loc ID 335078 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sghan@vnreenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnreenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211294	WELL	PR	09/12/1996	GW	045-07053	PORTER FEDERAL 14-28-6-92	PR
279923	WELL	PR	08/16/2006	GW	045-11108	SPECIALTY FEDERAL 24D-28-692	PR
279924	WELL	PR	08/17/2006	GW	045-11109	SPECIALTY FEDERAL 24C-28-692	PR
279925	WELL	PR	08/09/2006	GW	045-11110	SPECIALTY FEDERAL 23A-28-692	PR

General Comment:

Routine Field Inspection.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	4- 55 gallon drums on North side of location have no markings on them. Talked with route pumper they were going to remove or possibly remark the drums.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Missing Barrel count on 400 bbl tanks, talked with route pumper, he was getting stickers to correct issue. Methanol barrel missing labels, pumper was taking care of this also.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	staining in North battery containment.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.		Date: 10/17/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fencing.		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panel fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	HEATED STEEL AST		,
Comment: Centralized battery, seperate battery					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES	
Comment:	Bradenhead valvels open	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211294 Type: WELL API Number: 045-07053 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 279923 Type: WELL API Number: 045-11108 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 279924 Type: WELL API Number: 045-11109 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 279925 Type: WELL API Number: 045-11110 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
Berms						
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301932	Inspection photo 689301932	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581346