

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2018

Submitted Date:

09/18/2018

Document Number:

689401624

**FIELD INSPECTION FORM**

Loc ID 312576 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 11 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	<a href="#">Operation Manager</a>
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	<a href="#">All Inspections</a>
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	<a href="#">Petroleum Engineer</a>
Engineering		dnr_cogccengineering@state.co.us	<a href="#">All Engineering</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221951	WELL	SI	09/01/1983	GW	077-08553	USA 1-22 C	TA

**General Comment:**

[This is a follow up inspection to FIR Doc#689401078. Any corrective actions not addressed from previous inspections are still applicable.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road has been washed out and not suitable for vehicle or workover equipment access. See attached photos.		
Corrective Action:	Repair and maintain lease road to comply with rule 204.	Date:	01/18/2019

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign has multiple bullet holes in it and is missing nearest public access. See photos.		
Corrective Action:	Install sign to comply with Rule 210	Date:	10/18/2018

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Vegetation around wellhead.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/18/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No	NO		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date:

<b>Flaring:</b>			
Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date:

**Inspected Facilities**

Facility ID: 221951 Type: WELL API Number: 077-08553 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Production records show well has been shut in since January 1999. No production equipment on site. Form 4 Doc#401175080 approved 1/5/17 for TA status. COA States: "Approval of this Sundry fulfills condition number 11 of Maralex ACO 1V-609. Per Rule 319 b.(1) Maralex will need to submit annual sundry notice for continued temporary abandonment stating the method by which the well is closed to the atmosphere and plans for future operation." No current Form 4 on file. Form 6 Doc#401479849 approved on 6/8/18 and will expire on 12/7/18

**Corrective Action:** A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Date: 03/27/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See access road section of inspection. Sediment migration and erosion of roadway and on south side of location would not meet the COGCC Stormwater rules. This location is a federal surface hence the inspection is being forwarded to a BLM representative so they may respond to the operator on what actions should be implemented.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401625	USA 1-22 C Follow up photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581582">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581582</a>