

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #1**

**Sooner Unit 6-21** wellhead  
Bradenhead NOT plumbed to surface  
Stained soil  
*From previous FIR*



**Photo #2**

**Sooner Unit 6-21** (API # 05-123-14562) wellhead  
**Bradenhead NOT plumbed to surface**  
**Stained soil**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #3**

**Sooner Unit 6-21** wellsite

**Stained soil at pump jack (N & S sides)**

*From previous FIR*



**Photo #4**

**Sooner Unit 6-21** wellsite

***New sign has been posted.***

**Stained soil at pump jack (N & S sides)**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



Colorado Oil & Gas Conservation Commission  
140.64921, -103.8701, 1420.0m, 156°  
2018/09/18 01:50:26 PM

**Photo #5**

**Sooner Unit 6-21** wellsite

**Unmarked Anchors**

*2 of 4 are marked*



07.07.2017 12:28

**Photo #6**

**Sooner Unit** Produced H2O tanks

**Debris near East produced H2O tanks remains**

*From previous FIR*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #7**

**Sooner Unit** Produced H2O tank room

**Debris near middle West produced H2O tank**



**Photo #8**

**Sooner Unit** Produced H2O tank room

**Debris near middle East produced H2O tank**





## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



Colorado Oil & Gas Conservation Commission  
40.65219, -103.87011, 1421.0m, 111°  
2018/09/18 02:49:16 PM

**Photo #9**

**Sooner Unit** North treater house

**Unused equipment**



Colorado Oil & Gas Conservation Commission  
40.65218, -103.87013, 1429.0m, 199°  
2018/09/18 02:49:30 PM

**Photo #10**

**Sooner Unit** North treater house

**Unused equipment - outside**

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #11**

**Sooner Unit** Produced H<sub>2</sub>O tank room – E. door

***Unused equipment***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #12**

**Sooner Unit** North treater

*Stained soil and previously leaking equip.*

*From previous FIR*



**Photo #13**

**Sooner Unit** North treater

*Stained soil and previously leaking equip.*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #14**

**Sooner Unit** North treater house

**Stained soil**

*From previous FIR*



**Photo #15**

**Sooner Unit** North treater house

**Stained soil**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #16**

**Sooner Unit** South treater house

***Stained soil***

*From previous FIR*



**Photo #17**

**Sooner Unit** South treater house

***Stained soil***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #18**

**Sooner Unit** Crude oil recycle pump

***Stained soil***

*From previous FIR*



**Photo #19**

**Sooner Unit** Crude oil recycle pump

***Stained soil***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #20**

**Sooner Unit** Produced H<sub>2</sub>O tanks N side.

***Stained soil***

*From previous FIR*



**Photo #21**

**Sooner Unit** Produced H<sub>2</sub>O tanks N side.

***Stained soil***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #22**

**Sooner Unit** Produced H<sub>2</sub>O transfer pumps

***Stained soil***



**Photo #23**

**Sooner Unit** Produced H<sub>2</sub>O transfer pumps

***Stained soil***





## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #24**

**Sooner Unit** Crude Oil tanks - loadout

***Stained soil***



**Photo #25**

**Sooner Unit** Crude Oil tanks - drain

***Stained soil***

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #26**

**Sooner Unit** Injection Pump – N side

**Stained floor**



**Photo #27**

**Sooner Unit** Injection Pump – S side

**Stained floor**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



**Photo #28**

**Sooner Unit** H2O pit – skim

***Culvert Rusted***



**Photo #29**

**Sooner Unit** H2O pit – skim

***Culvert rusted***



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** Sooner Unit - 68N58W /21SENW

**Location #:** 327361



Colorado Oil & Gas Conservation Commission  
40.65173, -103.87041, 1416.0m, 37°  
2018/09/18 02:43:03 PM

**Photo #30**

**Sooner Unit** Battery



Colorado Oil & Gas Conservation Commission  
40.65201, -103.87016, 1422.0m, 359°  
2018/09/18 02:45:20 PM

**Photo #31**

**Sooner Unit** Treaters



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources