

**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Location photo. Dead weed debris.**

Bosley SG 43-22  
API# 05-045-07243  
Inspection# 689701810



Tank volume added to label.



**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Ditch repaired on channeling and cleared of sediment.**

**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Dead weed debris**



**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Dead weed debris.**

**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Sediment build up in ditch between tank and separators.**



**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Sediment movement and build up.**



**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Erosion of culvert basin by separators.**



**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Movement of sediment behind separators.**

**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Repair made to shoulder.**



**Bosley SG 43-22**  
**API# 05-045-07243**  
**Inspection# 689701810**



**Loose earth material along shoulders**