

# *Inspection Photos*

*Loc#413754*

*Operator: Sandridge*

*Inspection Number: 692400129*

*Inspection Date: 9/14/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
Overview of Location from entry to Northwest.

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron/Marr Loc#413754



Photo#2:  
Noxious weed, Canada thistle is established on outside of West Berm.

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron/Marr Loc#413754





**Photo#3:**

There is evidence of heavy Annual Weed Growth on Location Berms. When these or any other vegetative material that could blow offsite or into equipment areas, are dead they are considered debris.

**Photo#4:**

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron/Marr Loc#413754






Photo#5:  
Staining of soil and Debris at Wellhead.

September14, 2018



Photo#6:





Photo#7:

Cellar of Well API#057-06556 was filled with what appears to be water topped with skim of Oily waste. No freeboard was present, stains outside of cellar showed where liquid had begun to discharge, before level subsided.

September14, 2018



Photo#8:



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron/Marr Loc#413754