

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2018

Submitted Date:

09/20/2018

Document Number:

690002457**FIELD INSPECTION FORM**Loc ID 327738 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247296	WELL	SI	05/01/2017	GW	123-15093	EISENACH & PRESTON 8-8K	SI
433286	WELL	PR	12/24/2013	OW	123-37571	EISENACH FEDERAL 30N-8HZ	PR
433288	WELL	PR	12/24/2013	OW	123-37572	EISENACH 32N-8HZ	PR
433291	WELL	PR	01/17/2014	OW	123-37573	EISENACH FEDERAL 30C-8HZ	PR
433293	WELL	PR	12/27/2013	OW	123-37574	EISENACH FEDERAL 5N-8HZ	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barb Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 3		

Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	5	300 BBLS	STEEL AST		40.241970,-104.794200	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type	Ignitor/Combustor	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**

Facility ID: 247296 Type: WELL API Number: 123-15093 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 433286 Type: WELL API Number: 123-37571 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 433288 Type: WELL API Number: 123-37572 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 433291 Type: WELL API Number: 123-37573 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 433293 Type: WELL API Number: 123-37574 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: [Bradenhead plumbed to surface.](#)

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection.</a>	carlilec	09/20/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690002458	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4584141">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4584141</a>