

# Inspection Photos

09/20/2018

Operator: SMITH OIL PROPERTIES INC - 79905

Location ID: 313873

Inspection Doc. Number: 682503911

Morgan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the south end of the well location, facing northwest. Photos 1-2 provide an overview of the well location. Photo shows various equipment and trash debris remain on site. Photo also shows no reclamation activities appear to have been conducted in accordance w/ 1004.a



**Photo 2:** Photo taken from the south end of the well location, facing north. Photos 1-2 provide an overview of the well location. Photo shows various equipment and trash debris remain on site. Photo also shows no reclamation activities appear to have been conducted in accordance w/ 1004.a




**Photo 3:** Photo taken from the south of the well location, facing north. Photo shows areas of disturbance off of the location that requires reclamation. Photo also shows various equipment and trash debris remain on site, and that no reclamation activities appear to have been conducted in accordance w/ 1004.a

Inspection Photos  
Operator: SMITH OIL PROPERTIES INC - 79905  
Location ID: 313873



**Photo 4:** Photo taken from the southwest of the well location, facing northeast. Photo shows area of a former spill that caused degradation on the adjacent lands. These areas require reclamation.

Inspection Photos  
Operator: SMITH OIL PROPERTIES INC - 79905  
Location ID: 313873



**Photo 5:** See comments under photo 4. 6 foot measuring stick for reference.



**Photo 6:** Photo taken from the west end of the well location, facing north. Operator appears to have installed straw wattles stormwater and sediment control BMPs. BMPs have not been maintained and are no longer in proper functioning conduction. Wattles are now considered debris and will need to be removed



**Photo 7:** Photo taken from the west end of the well location. Photo shows Scotch Thistle. This is a Colorado State listed Noxious weed and required management.



**Photo 8:** Photo taken from the west end of the well location, facing northeast. Photo shows various debris and equipment remaining on location.



**Photo 9:** Photo taken from the west end of the well location, facing east. Photo shows various debris and equipment remaining on location. Photo also shows no reclamation activities appear to have been conducted in accordance w/ 1004.a

Inspection Photos  
Operator: SMITH OIL PROPERTIES INC - 79905  
Location ID: 313873



**Photo 10:** Photo taken from the north end of the well location, facing south. See comments under photo 9.



**Photo 11:** Photo taken from the north end of the well, facing southwest. Photo shows areas of contaminated soils observed on the location. 6 foot measuring stick for reference.



**Photo 12:** Photo taken from the south end of the well, facing west. See comments under photo 11.



**Photo 13:** Photo taken from the west of the pit location, facing north. Photo shows areas of the closed pit that remained unvegetated. These areas require reclamation. Additional remediation may be required.



**Photo 14:** Photo taken from the west of the pit location, facing east. Photo shows areas of the closed pit that remained unvegetated. These areas require reclamation. Additional remediation may be required.



**Photo 15:** Photo taken from the west of the pit location, facing northeast. Photo shows Scotch Thistle. This is a Colorado State listed Noxious weed and required management.

Inspection Photos  
Operator: SMITH OIL PROPERTIES INC - 79905  
Location ID: 313873



**Photo 16:** Photo taken from the east end of the skim pit, facing west.



**Photo 17:** Photo taken from the skim pit. Photo of contaminated soils. 6 foot measuring stick reference.



**Photo 18:** Photo taken from the skim pit. Photo of contaminated soils. 6 foot measuring stick reference.



**Photo 19:** Photo taken from the northeast end of the pit, facing southwest. Photo shows overview of the pits. Pits remain open and have not been reclaimed.



**Photo 20:** Photo taken from the northeast end of the pit, facing west. Photo shows overview of the pits. Pits remain open and have not been reclaimed. .



**Photo 21:** Photo taken from the north end of the battery location, facing west. Photo shows areas where contaminated soils were once stored. Tarp remains on site. 6 foot measuring stick for reference.



**Photo 22:** Photo taken from the northwest end of the battery location, facing south. Photo shows battery location has not been reclaimed. 6 foot measuring stick for reference.



**Photo 23:** Photo taken from the northwest end of the battery location, facing east. Photo shows battery location has not been reclaimed. 6 foot measuring stick for reference.



**Photo 24:** Photo taken from the northwest end of the battery. Photo shows anchor remaining on site.



**Photo 25:** Photo taken from the west end of the battery location. Photo shows contaminated soils on the battery location. 6 foot measuring stick for reference.



**Photo 26:** Photo taken from the southern end of the battery. Photo shows a pile of soil stored on locaiton.



**Photo 27:** Photo taken from the west end of the battery, facing southwest. Photo shows area of access road leading from the well to the battery. Photo shows access road has not been reclaimed. Erosion degradation evident.



**Photo 28:** Photo taken from the southwest of the battery. Photo shows area of a previous spill. Photo shows area remains predominantly bare and exposed soil. Area requires remediation/reclamation.



**Photo 29:** Photo taken from the east of the location. Photo shows area where a second access road to the location has been reclaimed.



**Photo 30:** Photo taken from the access road, south of the location. Photo shows access road has not been reclaimed or maintained.



**Photo 31:** Photo taken from the access road, south of the location. Photo shows access road has not been reclaimed or maintained; erosion degradation evident.



**Photo 32:** Photo taken from the access road, south of the location. Photo shows access road has not been reclaimed or maintained; erosion degradation evident.