

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 2. Stained soil at tank loadout.
9/20/2018



Photo 3. Stained soil at tank loadout.
7/12/2018

Inspection Photos
Location Name: USA Shaw 19
API: 05-081-60020



Photo 4. Fluid in cellar.
9/20/2018



Photo 5. Fluid in cellar.
7/12/2018