

Inspection Photos

Operator: DJ Simmons Inc.

API: 05-033-06008

Date: 9/18/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing within outer reclamation areas with grass such as smooth brome (*Bromus inermis*) and shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 3. View of the southern portion of the project area from the southwestern edge facing eastward.



Photo 4. View of tanks in the northeastern project area.



Photo 5. View of tall kochia plants (*Kochia scoparia*) in the eastern project area. These should be removed as they will dry, break off, and become debris.