

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2018

Submitted Date:

09/24/2018

Document Number:

689801660**FIELD INSPECTION FORM**Loc ID 413754 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412904	WELL	PR	04/15/2014	OW	057-06499	HEBRON 02-07H	PR
412906	WELL	DG	02/27/2017	LO	057-06497	Marr 0780 1-6H31	WO
446421	WELL	DG	08/14/2016	OW	057-06557	Marr 0780 5-6H31	WO
446422	WELL	DG	08/12/2016	OW	057-06558	Marr 0780 6-6H31	WO
447274	WELL	DG	08/18/2016	OW	057-06575	Marr 0780 2-6H31	WO

**General Comment:**[Routine FIU inspection.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 405-429-5974

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Other	WELLHEAD	<= 1 bbl	
Comment:	Multiple stained soil spots around and immediately adjacent to wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 10/25/2018
Other	WELLHEAD	>= 5 bbls	
Comment:	Cellar of Well API#057-06556 was filled with what appears to be water topped with skim of oily waste. No freeboard was present, stains outside of cellar showed where liquid had begun to discharge, before level subsided.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Remove free fluids and contact COGCC EPS staff per Rule 906.b. Initial Form 19 Report by 9/24/18. Remove stained soil by 10/20/18.		Date: 09/21/2018

In Containment: No

Comment: Inspector contacted operator in the field and showed them spill. When inspector left location operator was waiting for vac truck.  
Please submit date and time stamped photos of dry cellar as an attachment with an FIRR.

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**

Facility ID: 412904	Type: WELL	API Number: 057-06499	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 412906	Type: WELL	API Number: 057-06497	Status: DG	Insp. Status: WO
---------------------	------------	-----------------------	------------	------------------

Facility ID: 446421	Type: WELL	API Number: 057-06557	Status: DG	Insp. Status: WO
---------------------	------------	-----------------------	------------	------------------

Facility ID: 446422	Type: WELL	API Number: 057-06558	Status: DG	Insp. Status: WO
---------------------	------------	-----------------------	------------	------------------

Facility ID: 447274	Type: WELL	API Number: 057-06575	Status: DG	Insp. Status: WO
---------------------	------------	-----------------------	------------	------------------

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. It appears stormwater being funneled into cellars of four uncompleted wells.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/24/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801661	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4586684">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4586684</a>