

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2018

Submitted Date:

09/24/2018

Document Number:

690100793

FIELD INSPECTION FORM

Loc ID 311302 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262378	WELL	SI	07/01/2018	GW	123-20743	CANNON FEDERAL 12-8A	EG

General Comment:

COGCC Inspector met with the Anadarko contract supervisor (from Nail Services) on location; crews are in progress of removing all flowlines associated with this well and facility. This well has been plugged and abandoned; form 42 notice of start of plugging operations Doc #401726631 was received on 08/07/2018. Details are available in the flowline section of this report. Photos uploaded.

Inspected Facilities

Facility ID: 262378 Type: WELL API Number: 123-20743 Status: SI Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: The off location wellhead flowlines (1) 2" carbon steel and (1) 1" poly flowline running approximately 1700' south from the wellhead to facility have been removed. The associated dump lines and process pipe (at facility) are being removed (2- 40' sections of 2" cs dump flowlines routed under existing tank berms are being abandoned in place/ solid filled with cement). Asbestos coating found on flowlines at the facility is being addressed by a separate contractor (abatement crew) and handled/ disposed of according to regulations. The facility (decommissioned/ equipment and tanks removed) is on a shared location (KPK); work is being conducted to avoid the other operations.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
COGCC form 42 notice of flowlines abandoned Doc #401762972 was recieved on 09/13/2018.	maclarej	09/24/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100805	Dump lines exposed (south of KPK battery)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4586901
690100806	Excavation at battery (tanks & equipment removed)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4586902