

Inspection Photos

Location Name: GMU-66S93W 26NENW Pad

Location ID: #335163

Inspection Date: September 25, 2018



Photo #1 – Lease sign located at NE corner of pad.



Photo #2 – Operator had vac truck on location during inspection.



Inspection Photos
Location Name: GMU-66S93W 26NENW Pad
Location ID: #335163
Inspection Date: September 25, 2018



Photo #3 – View of impacted tank from NE corner.



Photo #4 – Fire damage extending up the side of the impacted tank.

Inspection Photos
Location Name: GMU-66S93W 26NENW Pad
Location ID: #335163
Inspection Date: September 25, 2018



Photo #5 – Tank battery liner was compromised at SE corner due to fire damage.



Photo #6 – Tank heater was pulled out of tank and being stored outside of tank battery berm on inspection date.