

Inspection Photos
Location Name: TEP 335123
9/19/2018



New welded pipeline segment



Dry soil below check dam looking SE



Wet soil above check dam looking NW



Release area to ditch looking NW