

**Inspection Photos**  
**Location Name: Champlin 367 Amoco 1**  
**Location ID: 318431**



**Photo 1 WH**



**Photo 2 TNK BTRY**

**Inspection Photos**  
**Location Name: Champlin 367 Amoco 1**  
**Location ID: 318431**



**Photo 3 old seals on loc**



**Photo 4 old metal panels on loc**

**Inspection Photos**  
**Location Name: Champlin 367 Amoco 1**  
**Location ID: 318431**



**Photo 5 TNK BTRY**

