

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2018

Submitted Date:

09/26/2018

Document Number:

685305359

**FIELD INSPECTION FORM**

Loc ID 326159 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Trujillo, Etta		ettrujillo@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215972	WELL	PR	05/03/1993	GW	067-07578	HUBER-WILBOURN 2-22	PR

**General Comment:**

Inspection completed as witness to riser/flowline abandonment and routine follow up inspection.  
This inspection does not alleviate requirement for operator to complete any open corrective actions from previous inspections.  
See link at end of report for path to downloadable pictures.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type UNUSED EQUIPMENT

Comment: Corrective action completed.

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 215972 Type: WELL API Number: 067-07578 Status: PR Insp. Status: PR

**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Other Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: 1" unused line identified during routine inspection. Line was excavated to below grade elbow connection and disconnected. Cotton material was inserted approximately 12"-18"into line and then filled with concrete. Steel plug installed in elbow. GPS coordinates W37.17021/W107.43716. T post with tracer wire placed at terminated end and area backfilled.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305444	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590184</a>