

# Construction and Stormwater Inspection

September 26, 2018

Operator: CCRP OPERATING INC- 10665

Location ID: 456179

Inspection Document #: 682404008

Weld County, CO

NENE Section 23 T12N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: True Ranch Fee /2326 East

Location ID: 456179



**Photo 1.** Photo taken from the entrance of the location, facing West. Operator plans to gravel the entrance to the well location to control for vehicle track out.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 2.** Photo taken from the northeastern perimeter of the location, facing West. Operator has salvaged and stored the topsoil along the northern perimeter. Operator plans to seed and mulch topsoil.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 3.** Photo taken from the northern location, facing West. Operator plans to install a perimeter BMP around the topsoil.



# Inspection Photos

Location Name: True Ranch Fee /2326 East

Location ID: 456179



**Photo 4.** Photo taken from the southwestern perimeter of the location, facing South. Operator failed to install stormwater BMPs prior to, or at, the start of construction. Operator installed the temporary stormwater BMP (ditch) during my inspection. This would not be considered a proper functioning BMP because unconsolidated material has not been properly stabilized. Unconsolidated material becomes a source of potential pollution itself. Operator plans to install silt fence as a permanent BMP.



Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 5.** Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 4.

Inspection Photos  
Location Name: True Ranch Fee /2326 East  
Location ID: 456179



**Photo 6.** Photo taken from the southeastern perimeter of the location, facing North.  
See comments under Photo 4.