

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2018

Submitted Date:

09/27/2018

Document Number:

689302001

FIELD INSPECTION FORM

Loc ID 334909 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270706	WELL	PR	06/17/2009	GW	045-09787	BROWN 11-2C (F11E)	PR
293456	WELL	PR	05/30/2009	GW	045-14999	ENCANA 11-3B2 (F11E)	PR
294723	WELL	PR	06/03/2009	GW	045-15578	ENCANA 11-5(F11E)	PR
294724	WELL	PR	06/07/2009	GW	045-15579	ENCANA 11-4C(F11E)	PR
294725	WELL	PR	06/05/2009	GW	045-15580	ENCANA 11-12A (F11E)	PR
294726	WELL	PR	05/31/2009	GW	045-15581	ENCANA 11-4D (F11E)	PR
299256	WELL	PR	06/11/2009	GW	045-17627	ENCANA FEDERAL 11-11A (F11E)	PR
299516	WELL	PR	05/25/2009	GW	045-17698	ENCANA 11-6(F11E)	PR
299517	WELL	PR	05/28/2009	GW	045-17699	ENCANA 11-6A(F11E)	PR
299518	WELL	PR	10/01/2017	GW	045-17700	ENCANA 11-3D(F11E)	PR

General Comment:

This is a follow up inspection from [Doc# 689301834](#). Required Corrective Action items noted in previous inspections have been satisfied.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date:

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	panel gates		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:

Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Vertical blow down tank.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 10	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	1 chemical unit at wellhead 1 chemical unit in battery containment 1 chemical unit at pigging station.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:	Centralized battery.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Methanol tank
Other (Capacity)	1000 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	270706	Type:	WELL	API Number:	045-09787	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	293456	Type:	WELL	API Number:	045-14999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	294723	Type:	WELL	API Number:	045-15578	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	294724	Type:	WELL	API Number:	045-15579	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	294725	Type:	WELL	API Number:	045-15580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	294726	Type:	WELL	API Number:	045-15581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	299256	Type:	WELL	API Number:	045-17627	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	299516	Type:	WELL	API Number:	045-17698	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 299517 Type: WELL API Number: 045-17699 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 299518 Type: WELL API Number: 045-17700 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
				Material Handling And Spill Prevention		
Seeding						
Slope Roughening						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302002	Inspection photo 689302002	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592331