

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2018

Submitted Date:

09/28/2018

Document Number:

690300342

FIELD INSPECTION FORM

Loc ID 390877 Inspector Name: Spencer, Stan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 5
Name of Operator: COLORADO OIL & GAS CONSERVATION
Address: 1120 LINCOLN ST SUITE 801
City: DENVER State: CO Zip: 80203

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	
Burger, Craig		craig.burger@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

Inspections for OWP program to assess current conditions of De Beque orphan wells prior to commencing P&A operations. On site with COGCC engineers, Craig Burger and Shannon Chollett. Weather clear, 75 F. Extremely dry conditions for both September and annual. Well has similar conditions to prior inspections. Well is flowing gas and water at estimated ~5gpm. 10-15 ft diameter pool is fenced with T-posts and two-strand barbed wire. Low concentrations of H2S have been detected at this well. Runoff to the south results in stressed/dead vegetation and iron staining. Discharge is to ditch and Roan Creek. Access via rough road bulldozed by landowner.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300343	Insp photos 9-27-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592615