

Inspector Name:

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2018

Submitted Date:

09/28/2018

Document Number:

688800291

FIELD INSPECTION FORM

Loc ID 312035 Inspector Name: _____ On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274149	WELL	PR	10/15/2004	GW	067-08983	SEMLER A 2	EI
292313	WELL	PR	12/01/2017	GW	067-09395	SEMLER A 4	EI

General Comment:

On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Semler A #4. For the most recent field inspection report of this facility, please refer to document #680602723. BP representative Julian Martinez was on location during this site visit.

Inspector Name:

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard and label posted on secondary containment ring for PBV.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel enclosure around pump jack for A #4. Guard fencing present.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel enclosure around all equipment on site.		
Corrective Action:		Date:	
Equipment:			
Type: Vertical Heated Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Weatherford air package on location at the time of this inspection. Semler A #2 was being manually unloaded. Equipment had 260 psi on it during this site visit.		
Corrective Action:		Date:	

Inspector Name:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.128540,-107.671268
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspector Name:

Inspected Facilities

Facility ID: 274149 Type: WELL API Number: 067-08983 Status: PR Insp. Status: EI

Facility ID: 292313 Type: WELL API Number: 067-09395 Status: PR Insp. Status: EI

Inspector Name: _____

Environmental

Spills/Releases:

Type of Spill: _____	Estimated Spill Volume: _____
Comment: <input style="width: 100%;" type="text"/>	
Corrective Action: <input style="width: 90%;" type="text"/>	Date: _____
Reportable: _____	GPS: Lat _____ Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____	Owner Name: _____	GPS : _____	Lat _____ Long _____
0310113	Adams	37.133336	-107.668840

Field Parameters:

Sample Location: _____	Comment: _____
------------------------	----------------

Inspector Name:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Semler A #4. For the most recent field inspection report of this facility, please refer to document #680602723. BP representative Julian Martinez was on location during this site visit.</p> <p>The Semler A #2 well was being manually unloaded during this inspection. A Weatherford air package was on location. The procedure was expected to take three or four days.</p>	hughesj	09/28/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800292	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592744