

Inspector Name:

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2018

Submitted Date:

09/28/2018

Document Number:

688800293

FIELD INSPECTION FORM

Loc ID 325796 Inspector Name: _____ On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215392	WELL	PR	04/26/1990	GW	067-06997	TILLMAN BURCH 1	EI

General Comment:

[On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Tillman Burch #1. For the most recent field inspection report of this facility, please refer to document #680602732.](#)

Inspector Name:

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Free standing sign near location was facing inward at the time of this inspection.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Irrigation pipe has been moved off of location.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Stock panel enclosure.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Stock panel enclosures around separator, meter run, and telemetry equipment.			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Telemetry			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:				

Inspector Name:

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215392	Type:	WELL	API Number:	067-06997	Status:	PR	Insp. Status:	EI

Inspector Name:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Tillman Burch #1. For the most recent field inspection report of this facility, please refer to document #680602732. Irrigation pipe noted in previous inspection has been moved off of the location.	hughesj	09/28/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800294	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592745