

Inspection Photos  
Location Name: Amoco-Federal 21-1  
API: 05-081-06439



**Photo 1. Overview of location taken at entrance facing west.**

Inspection Photos  
Location Name: Amoco-Federal 21-1  
API: 05-081-06439



Photo 2. Label falling off left hand tank.



Photo 3. Spill photo 1 of 6. Standing at western edge of tank berm.

Inspection Photos  
Location Name: Amoco-Federal 21-1  
API: 05-081-06439



Photo 4. Spill photo 2 of 6.



Photo 5. Spill photo 3 of 6.



Inspection Photos  
Location Name: Amoco-Federal 21-1  
API: 05-081-06439



Photo 6. Spill photo 4 of 6. Sheen visible on water.



Photo 7. Spill photo 5 of 6. Standing on eastern edge of tank berm looking west.

Inspection Photos  
Location Name: Amoco-Federal 21-1  
API: 05-081-06439



**Photo 8. Spill photo 6 of 6. Not 2 feet of freeboard, netting sagging into contents.**



**Photo 9. Stained soil at pump jack exhaust.**



Inspection Photos  
Location Name: Amoco-Federal 21-1  
API: 05-081-06439



**Photo 10. Second pit on location.**



**Photo 11. Partially buried tank in fenced area with pit.**