

Inspection Photos

Operator: BP America

API: 05-067-08898

Date: 9/25/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the northern cut slope from the central toe of slope facing up-slope. Vegetation is sparse and significant rilling/run-on is occurring.



Photo 4. Closeup view of rilling on the northern cut-slope up to 10 inches wide and deep. Run-on controls, erosion controls such as erosion blankets, and cattle exclusion are likely needed to stabilize slope. Seeding is needed where vegetation is not becoming established.



Photo 6. View of erosional channel approximately 1.5 feet wide and deep, in the northeastern project area where a drainage flows along the eastern edge of the project area and is resulting in erosional downcutting.



Photo 7. View of rock run-down in the southern project area.



Photo 8. View of rilling in the southern cut-slope, facing down-slope.



Photo 9. View of cobble armoring in the northwestern corner of the working area where stormwater is diverted off of the northern project area.