

Inspection Photos

Operator: BP America

API: 05-067-08897

Date: 9/25/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the northern project area from the northwestern corner facing eastward. Revegetation is largely grazed, and comprised with grasses such as intermediate wheatgrass (*Thinopyron intermedium*) and western wheatgrass (*Pascopyrum smithii*), as well as shrubs such as antelope bitterbrush (*Purshia tridentata*).





Photo 5. View of erosional rilling in the northeastern project area. It is not apparent whether area is actively eroding and needs to be monitored.