

Inspection Photos

Operator: BP America

API: 05-067-08880

Date: 9/25/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of area on the western cut-slope with poor revegetation. This needs to be monitored and if revegetation is not progressing , the further seeding and reclamation efforts will be required.



Photo 5. View of erosional channel up to 3 feet deep and 4 feet wide, in the southwestern project area. Wattles are not sufficient for stabilizing this portion of the project area.