

Inspection Photos
Location Name: Shock-Federal 1
API: 05-057-06351



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351



Photo 2. No wildlife protection on separator exhaust.



**Photo 3. No wildlife protection on separator exhaust.
8/25/2017 Inspection document number 689800233**

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351



Photo 4. Pit.



Photo 5. Pit.

8/25/2017 Inspection document number 689800233

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351




Photo 6. 2" steel riser.



Photo 7. 2" steel riser.

8/25/2017 Inspection document number 689800233

Inspection Photos
Location Name: Schock-Federal 1
API: 05-057-06351



Photo 8. Stained soil at loadout.



**Photo 9. Stained soil at loadout.
8/25/2017 Inspection document number 689800233**