

Inspection Photos

Operator: BP America

API: 05-067-07069

Date: 9/25/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward.



Photo 3. View of the western project area from the southwestern corner facing northward. Interim reclamation areas appear to be recently reclaimed. Grasses and forbs such as western wheatgrass (*Pascopyrum smithii*) and blue flax (*Linum lewisii*) are becoming established. Straw mulch is still in place.



Photo 4. View of the eastern project area from the southeastern project area facing northward.



Photo 5. View musk thistles (*Carduus nutans*) within the project area. Approximately 150 individuals observed.



Photo 6. View of cobble run-down in the southeastern project area, appears to be functioning at this time.