

Interim Reclamation and Stormwater Inspection

September 26, 2018

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 438066

Inspection Document #: 682404010

Weld County, CO

NENW Section 28 T12N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RAILAY /28-3-1CH
Location ID: 438066



Photo 1. Photo taken from the southern location, facing West. Germination of desirable species was observed. At a minimum, the Operator needs to control the weedy, annual vegetation (Russian thistle) per Rule 603.f. Some areas were observed with little to no germination which may require additional work if no progress is observed.



Photo 2. Photo taken from the southwestern location, facing East. Photo illustrates weedy, annual vegetation (Russian thistle). See comments under Photo 1.

Inspection Photos
Location Name: RAILAY /28-3-1CH
Location ID: 438066



Photo 3. Photo taken from the southwestern location, facing West. See comments under Photo 1.



Photo 4. Photo taken from the western location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: RAILAY /28-3-1CH
Location ID: 438066



Photo 5. Photo taken from the southern location, facing West. Stormwater BMP maintenance is required as the sediment trap is not in proper functioning condition.



Photo 6. Photo taken from the southern location, facing North. Rill erosion forming along the southern fill slope. Stormwater repairs are required.