

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2018

Submitted Date:

10/02/2018

Document Number:

689302034**FIELD INSPECTION FORM**
 Loc ID 334593 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|--|
| Elsener, | | COGCC.inspections@caerus oilandgas.com | all Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 257218 | WELL | PR | 02/08/2001 | GW | 045-07534 | ROLES 13-14 | PR |
| 257220 | WELL | PR | 06/01/2002 | GW | 045-07536 | ROE 13-13 | PR |
| 257221 | WELL | SI | 12/01/2008 | GW | 045-07537 | ROE 13-12 | TA |
| 258297 | WELL | PR | 06/01/2002 | GW | 045-07634 | ROLES 13-11R (N13) | PR |

General Comment:[Routine Field Inspection](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------------------------|----------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | 1-800-791-7691 | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------|-------|--|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|--|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Panel gates | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel gates | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---------------------|----------|-----------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | , | |
| Comment: | Centralized battery | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|---------------|--|
| Condition | Adequate | |
| Other (Content) | Methanol tank | |
| Other (Capacity) | 1000 gallon | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 257218 Type: WELL API Number: 045-07534 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 257220 Type: WELL API Number: 045-07536 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 257221 Type: WELL API Number: 045-07537 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment: MIT current and is on file, expires Oct 2018.
No Form 4 on file for continued TA status. Per 319-b.1

Corrective Action:

A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.Date: 11/02/2018Facility ID: 258297 Type: WELL API Number: 045-07634 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift

Corrective Action:

Date:

| Environmental | |
|-----------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): NO | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | | | | |
| Ditches | | | | | | |
| Retention Ponds | | | | | | |
| Seeding | | | | | | |
| Berms | | | | | | |
| | | Compaction | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 689302035 | Inspection photo 689302035 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4595951 |