

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2018

Submitted Date:

10/03/2018

Document Number:

689302050**FIELD INSPECTION FORM**

|  |                                 |   |                   |  |
|--|---------------------------------|---|-------------------|--|
| Loc ID<br>324140   | Inspector Name:<br>Holtz, Darin | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>11 Number of Comments<br>2 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>OGCC Operator Number: <u>96850</u><br>Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u><br>Address: <u>PO BOX 370</u><br>City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u> |                                 |   |                   |  |

**Contact Information:**

| Contact Name | Phone | Email                              | Comment                         |
|--------------|-------|------------------------------------|---------------------------------|
| Rocky, TEP   |       | COGCCInspectionReports@terraep.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 258999      | WELL | PR     | 07/10/2001  | GW         | 045-07680 | SAVAGE RMV 121-27 | PR          |

**General Comment:**[Routine Field Inspection.](#)

| Location   |   |        |                  |
|--|---|--------|------------------|
| <b>Lease Road:</b>                                     |   |        |                  |
| Type   | Access  |        |                  |
| comment:   |   |        |                  |
| Corrective Action                                      | L   |        | Date:            |
| Overall Good: <input checked="" type="checkbox"/>      |   |        |                  |
| Emergency Contact Number:                              |   |        |                  |
| Comment:   | 1-970-285-9377  |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| <b>Good Housekeeping:</b>                              |   |        |                  |
| Type   | WEEDS   |        |                  |
| Comment:   | uncontrolled weeds on location, see photo                     |        |                  |
| Corrective Action:                                     | Comply with Rule 603.f .                                      |        | Date: 10/15/2018 |
| Type   | UNUSED EQUIPMENT  |        |                  |
| Comment:   | Unused equipment near tank battery, see photo                 |        |                  |
| Corrective Action:                                     | Comply with Rule 603.f .                                      |        | Date: 11/03/2018 |
| Overall Good: <input type="checkbox"/>                 |   |        |                  |
| <b>Spills:</b>   |   |        |                  |
| Type   | Area  | Volume |                  |
| In Containment: No                                     |   |        |                  |
| Comment:   |   |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |                  |
| <b>Fencing/:</b>                                       |   |        |                  |
| Type   | TANK BATTERY  |        |                  |
| Comment:   | hog panel fencing.  |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Type   | WELLHEAD  |        |                  |
| Comment:   | hog panel fencing.  |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Type   | SEPARATOR   |        |                  |
| Comment:   | hog panel fencing.  |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| <b>Equipment:</b>                                      |   |        |                  |
| Type: Deadman # & Marked                               | # 3   |        | corrective date  |
| Comment:   |   |        |                  |
| Corrective Action:                                     |   |        | Date:            |
| Type: Ancillary equipment                              | # 3   |        |                  |
| Comment:   | 2 chemical units at wellhead<br>1 chemical unit at meter run. |        |                  |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Corrective Action:                |     | Date: |  |
| Type: Bird Protectors             | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Plunger Lift                | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |
| Type: Gas Meter Run               | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

| Contents           | #           | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|-------------|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1           | <100 BBLs | STEEL AST |         | ,      |
| Comment:           | 80 bbl tank |           |           |         |        |
| Corrective Action: |             |           |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |                                |       |      |             |           |         |    |               |    |
|----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 258999                         | Type: | WELL | API Number: | 045-07680 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                                |       |      |             |           |         |    |               |    |
| Comment:             | Well Producing on plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                |       |      |             |           | Date:   |    |               |    |

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL   |
|--------------|-------------------------------|---|
| 689302051    | Inspection photo<br>689302051 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597176</a> |