

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2018

Submitted Date:

10/03/2018

Document Number:

685305480

**FIELD INSPECTION FORM**

Loc ID 320849 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	<a href="#">All Inspections</a>
Rabinowitz, Daniel	970-385-1363	drabinow@blm.gov	<a href="#">Durango</a>
Telecky, Barbara		btelecky@blm.gov	<a href="#">Durango</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205221	WELL	SI	11/26/2012	GW	007-06098	PARGIN MTN UT 2	SI

**General Comment:**

Inspection completed as witness for MIT requirement. Operator to submit completed Form 21 and well test chart.  
This inspection does not alleviate requirement for operator to complete any open corrective actions from previous inspections.  
See link at end of report for path to downloadable pictures.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 205221 Type: WELL API Number: 007-06098 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI. Previous successful MIT completed 10/24/2012  
MIT 10/02/2018 - Pass  
Initial casing pressure - 22 psig  
Casing pressured up to - 322 psig  
5 min - 322 psig  
10 min - 321 psig  
15 min - 321 psig  
20 min - 321 psig  
Total loss - 1 psig

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: Initial Braden Head pressure - 0 psig  
Braden Head blew down in 1 sec.  
Starting pressure - 0psig  
Ending pressure - 0 psig  
Shut in pressure - 0 psig

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment: [Stormwater BMPs appear to be properly installed and functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305530	Wellhead sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597606">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597606</a>
685305531	Well test chart.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597607">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597607</a>