

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2018

Submitted Date:

09/27/2018

Document Number:

689401640

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: CONKLIN, CURTIS On-Site Inspection   
312610 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
Engineering		dnr_cogccengineering@state.co.us	All Engineering
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222012	WELL	SI	05/01/2010	GW	077-08614	SOUTH SHALE RIDGE 5-23	TA

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is listed on AOC 1V-609

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign is with Pump Jack that has been removed from well.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds and vegetation covering location and around wellhead. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/08/2018
Type	STORAGE OF SUPL		
Comment:	Production equipment and tank have been disconnected and moved to side of location.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222012 Type: WELL API Number: 077-08614 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Equipment removed from well noted on previous inspection Doc#689400348 from 9/26/17. No current Form 4 on file for continued TA status. A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. According to AOC 1V-609 order #11 annual submission is still required. No MIT on file. A mechanical integrity test shall be performed on each temporarily abandoned well within 30 days of temporarily abandoning the well.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan. Date: 10/08/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401775991	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590565">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590565</a>
689401647	South Shale Ridge 5-23 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590557">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590557</a>