

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2018

Submitted Date:

10/03/2018

Document Number:

689801715**FIELD INSPECTION FORM**Loc ID 313180 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Maneotis, Karen	970-620-6099	Karen_Maneotis@swn.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270246	WELL	TA	08/05/2013	GW	081-07156	WALKER 3-43	TA

**General Comment:**[Routine FIU inspection.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Road becoming overgrown.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	1-877-879-0376			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Tubing next to unmarked risers.			
Corrective Action:	Comply with Rule 603.f .			Date: 11/05/2018
Type	UNUSED EQUIPMENT			
Comment:	2 - 2" steel risers at 40.58541, -107.81261 and 3 - 2" steel risers at wellhead not marked for abandonment or LOTO. Flowline risers not LO/TO or marked are considered unused equipment			
Corrective Action:	Comply with Rule 603.f .			Date: 11/05/2018
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Deadman # & Marked	# 4			corrective date
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 270246 Type: WELL API Number: 081-07156 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Sundry notice for continued TA status submitted 3/14/2018 document number 401506184.Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801725	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4598032">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4598032</a>