

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2018

Submitted Date:

10/03/2018

Document Number:

689801716**FIELD INSPECTION FORM**Loc ID 313155 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone        | Email                     | Comment                         |
|-----------------|--------------|---------------------------|---------------------------------|
| Maneotis, Karen | 970-620-6099 | Karen_Maneotis@swn.com    | <a href="#">All Inspections</a> |
| Pesicka, Conor  |              | conor.pesicka@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 264522      | WELL | TA     | 08/05/2013  | GW         | 081-07098 | WALKER 3-4    | TA          |

**General Comment:**[Routine FIU inspection.](#)

**Location**Overall Good: ☐**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |                |       |  |
|--------------------|----------------|-------|--|
| Comment:           | 1-877-879-0376 | Date: |  |
| Corrective Action: |                |       |  |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | UNUSED EQUIPMENT   |       |            |
| Comment:           | 2 - 2" steel risers at wellhead not marked for abandonment or LOTO.<br>Flowline risers not LO/TO or marked are considered unused equipment |       |            |
| Corrective Action: | Comply with Rule 603.f .   | Date: | 11/05/2018 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked | # 4 |       | corrective date |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |        |       |      |             |           |         |    |               |    |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:  | 264522 | Type: | WELL | API Number: | 081-07098 | Status: | TA | Insp. Status: | TA |
| Idle Well   |        |       |      |             |           |         |    |               |    |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned |        |       |      |             |           |         |    |               |    |
| Reminder: _____   |        |       |      |             |           |         |    |               |    |
| Comment: Sundry notice for continued TA status submitted 3/14/2018 document number 401506180.       |        |       |      |             |           |         |    |               |    |
| Corrective Action: _____  |        |       |      |             |           |         |    |               |    |
| Date: _____   |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689801726    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4598033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4598033</a> |