

Inspection Photos

Operator: BP America

API: 05-067-06904

Date: 9/25/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing, largely with grasses such as smooth brome (*Bromus inermis*).



Photo 3. View of erosional channel in the eastern fill slope, appears to be partially stabilized with cobble. This needs to be monitored and additional erosion controls applied if active erosion is occurring.



Photo 4. View of the western project area from the southwestern corner facing northward.