

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302056**



Location Photo #1



Location Photo #2

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302056**



Location Photo #3, 2 unmarked/unused flow line risers



Location Photo #4, unmarked/unused flow line riser

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302056**



Location Photo #5, Sediment moving onto location



Location Photo #6



**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302056**



Location Photo #7, sediment being moved onto location.



Location Photo #8, sediment being moved onto location.

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302056**



Location Photo #9, non stabilized slope near south side of battery.

