

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2018

Submitted Date:

10/04/2018

Document Number:

688400350**FIELD INSPECTION FORM**

Loc ID 319973 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone          | Email                   | Comment                         |
|----------------|----------------|-------------------------|---------------------------------|
| Fritzler, Gene | (970) 867-9388 | gfritzler@bresnan.net   | <a href="#">All Inspections</a> |
| Gomez, Jason   |                | jason.gomez@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 202067      | WELL | PR     | 01/01/2018  | OW         | 001-07472 | SIMPSON A 12  | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |           |       |  |
|--------------------|-----------|-------|--|
| <b>Fencing/:</b>   |           |       |  |
| Type               | PUMP JACK |       |  |
| Comment:           | Rod Iron  |       |  |
| Corrective Action: |           | Date: |  |

|                           |                |       |                 |
|---------------------------|----------------|-------|-----------------|
| <b>Equipment:</b>         |                |       | corrective date |
| Type: Pump Jack           | #              |       |                 |
| Comment:                  |                |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Ancillary equipment | # 1            |       |                 |
| Comment:                  | Electric panel |       |                 |
| Corrective Action:        |                | Date: |                 |
| Type: Prime Mover         | #              |       |                 |
| Comment:                  | Electric motor |       |                 |
| Corrective Action:        |                | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 202067         | Type: WELL | API Number: 001-07472 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 688400351    | loc pic     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599118</a> |