

**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Weeds**



**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Volumes need fixed.**

**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Sediment in ditch along cut slope.**



**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Seeding needed on sut slope.**

**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Sediment in ditch.**



**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Washing across road into check dam.**



**GM 42-27**  
**Api# 045-07593**  
**Inspection # 689701882**



**Sediment and water build up on main road and entrance road to MV 29-27 pad**