

# Construction and Stormwater Inspection

October 4, 2018

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 456151

Inspection Document #: 682404046

Weld County, CO

Lot 2 Section 31 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: Hester Farms II /31-H Pad**  
**Location ID: 456151**



**Photo 1.** Photo taken from the southeast perimeter of the location, facing West. Ditch and berm BMP has been installed around the entire perimeter of the location. Rill erosion was observed along the southern, eastern and western fill slope areas, but did not discharge off location.



**Photo 2.** Photo taken from the southeast perimeter of the location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: Hester Farms II /31-H Pad  
Location ID: 456151



**Photo 3.** Photo taken from the eastern location, facing North. Operator has salvaged and stored topsoil along the eastern perimeter of the location. Topsoil has been temporarily stabilized with equipment tracking.



**Photo 4.** Photo taken from the northeast perimeter of the location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: Hester Farms II /31-H Pad  
Location ID: 456151



**Photo 5.** Photo taken from the northwest perimeter of the location, facing South. See comments under Photo 1.



**Photo 6.** Photo taken from the western location. Photo illustrates rill erosion.

Inspection Photos  
Location Name: Hester Farms II /31-H Pad  
Location ID: 456151



**Photo 7.** Photo taken from the southern perimeter of the location, facing East. See comments under Photo 1. Note: Vehicle traffic should remain off BMPs as this could cause damage to the BMPs.