

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2018

Submitted Date:

10/05/2018

Document Number:

693200067

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Murray, Richard On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Arauzo, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist
Caerus		COGCC.inspections@caerusoilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457694	SPILL OR RELEASE	AC	09/28/2018		-	West Fork 3-Phase Line	AC

General Comment:

Joint inspection with Steven Arauzo and Richard Murray

Engineering Integrity Inspection performed on September 1, 2018. In response to initial form 19 spill report Doc #401778075

Inspected Facilities

Facility ID: 457694 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

Flowline

#1	Type: <u>Process Piping</u>	of Lines	
----	-----------------------------	----------	--

Flowline Description

Flowline Type: Process Piping Size: 10" Material: Carbon Steel
 Variance: Age: 5-10 Yrs Contents: Multiphase

Integrity Summary

Failures: Internal Corrosion Spills: Yes Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: At time of inspection 10"- 3 phase line was exposed. Release point in flowline was found. Smart Pig was run and results expected November 1st.

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200068	Caerus 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599862
693200069	Caerus 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599863