

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2018

Submitted Date:

10/05/2018

Document Number:

693200070

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Murray, Richard On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Caerus		COGCC.inspections@caerusoilandgas.com	All Piceance inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Arauza, Steven		steven.arauza@state.co.us	West Environmental Protection Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457694	SPILL OR RELEASE	AC	09/28/2018		-	West Fork 3-Phase Line	AC

General Comment:

Engineering Integrity Inspection performed on September 2, 2018. In response to initial form 19 spill report Doc #401778075

Inspected Facilities

Facility ID: 457694 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

Flowline

#1	Type: Process Piping	of Lines
----	----------------------	----------

Flowline Description

Flowline Type: Process Piping Size: 10" Material: Carbon Steel
 Variance: Age: 5-10 Yrs Contents: Multiphase

Integrity Summary

Failures: Internal Corrosion Spills: Yes Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 40' of 10"- 3 phase pipe was cut out plus 2' pup section. Witnessed Camera tool running down pipe 200 feet to the west and 270 feet to the east, pitting was observed and more pipe will need to be removed.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200071	Caerus 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599864
693200072	Caerus 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599865