

Inspection Photos

10/04/2018

Operator: WESTERN OPERATING COMPANY #
95620

Location ID: 312292

Inspection Doc. Number: 682503985
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the south end of the location, facing west. Photo 1-2 provides overview of the area of degradation to the south of the pits.



Photo 2: : Photo taken from the south end of the location, facing south

Inspection Photos
Operator: WESTERN OPERATING COMPANY # 95620
Location ID: 312292



Photo 3: Photo taken from the southeast end of the pit, facing north towards the well. Photo shows areas of the interim that operator previously regraded and seeded. Operator failed to implement required stabilization or stormwater and erosion control BMPs per CAs. Photo shows erosion degradation has been allowed to continue. 6 foot measuring stick for reference



Photo 4: Photo taken from the southeast end of the pit, facing north towards the well. Photo shows areas of the interim that operator previously regraded and seeded. Photo shows Operator has failed to implement required stabilization, stormwater and erosion control BMPs per Cas; erosion degradation has been allowed to continue. 6 foot measuring stick for reference.



Photo 5: Photo taken from the southeast corner of the pit, facing south. See comments under photo 4.



Photo 6: Photo taken from the southwest corner of the pit, facing west. See comments under photo 4



Photo 7: Photo taken from the southwest corner of the pit, facing northwest. See comments under photo 4



Photo 8: Photo taken from the southwest corner of the pit, facing southeast. See comments under photo 4



Photo 9: Photo taken from the west of the pit, facing west. See comments under photo 4



Photo 10: Photo taken from the west of the pit, facing east. See comments under photo 4



Photo 11: Photo taken from the east end of the pit, facing west. Photo shows erosion degradation (gully) has reformed. Production areas have not been sufficiently stabilized.



Photo 12: Photo taken from the cattle guard at the access road entrance. Photo shows erosion degradation has not been repaired; stormwater erosion has cut underneath the cattle guard.



Photo 13: Photo taken from the cattle guard at the access road entrance. Photo shows erosion degradation has not been repaired; stormwater erosion has cut underneath the cattle guard.