

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2018

Submitted Date:

10/05/2018

Document Number:

685305538**FIELD INSPECTION FORM**Loc ID 334275 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Baca, Matthew		matthew.baca@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215774	WELL	PR	08/17/2000	GW	067-07379	EVERETT JONES 1	PR
264607	WELL	PR	11/11/2002	GW	067-08750	JONES, EVERETT GAS UNIT 2	PR

General Comment:[Inspection completed as routine inspection requirement.](#)[This inspection does not alleviate requirement for operator to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Kochia is growing on graveled area of location. As seasonal changes take affect Kochia will die and dry out contributing to debris on location. Kochia will need to be removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Steel mesh safety barrier.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electrical control equipment - Stock panel fencing.		
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:	Stock panel fencing. Includes gas meter run.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Stock panel fencing.			
Corrective Action:			Date:	
Equipment:				corrective date
Type: Ancillary equipment	# 2			
Comment:	Electric control equipment.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Telemetry equipment.			
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 2			
Comment:	#1 In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located. In use - 6" steel line from separator outlet to gas meter inlet. All points co-located.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	#2 In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located.			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Linear rod pump.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Electrical supply equipment.			
Corrective Action:			Date:	
Type: Prime Mover	# 2			
Comment:	Electric motor.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			

Comment:	Wellhead.		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 6			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 215774 Type: WELL API Number: 067-07379 Status: PR Insp. Status: PR**Producing Well**Comment: PR.

Corrective Action:

Date:

Facility ID: 264607 Type: WELL API Number: 067-08750 Status: PR Insp. Status: PR**Producing Well**Comment: PR.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass					
Ditches	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: [Stormwater BMPs appear to be properly installed and functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305549	Wellhead signs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600106
685305550	Location overview.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600107